

## **Genuine Accessories**



Hardware Total

## **Genuine Accessories**



Any visible gaps should not exceed 0.5mm.

fter the installation, check for any visible gaps.

If any gap exceeds 0.5mm, loosen the mounting screws and refit the mudguard to the body to achieve the correct specification. Be careful not to over-tighten or strip the head of the screw.