

#### Vehicle Model: Santa Fe

Rev. Date 4/8/2019

Model Year 2019~ Part No. S2F62 AU000 (DIO) S2F62 AU600 (PIO) Language English

Difficulty: (B)

Accessory:

Note: Difficulty stated above reflects the minimum level of expertise required to install the accessory:

Mirror, Auto-dimming w/ HomeLink 4,

- (A) Customer
- (B) Dealer Technician
- (C) Master Technician or Specialist

Denotes personal protective equipment (PPEs) that

may be required for a step. Examples of safety equipment icons noted below:

**Bluelink and Compass** 



If this is a printed copy of the installation instructions, ensure you have the latest revision by scanning the QR code or by entering the website address listed below before beginning installation. Use the latest revision date as noted by "Rev. Date" above

 $www.hyundaiaccessories.com/admin\_media\_uploads/installationSheets/s2f62\_au000.pdf$ 

#### Application Notes

This accessory mirror kit is only applicable to vehicles built AFTER 22 Oct. 2018, VIN ...055982 with prewired factory 10-Pin mirror connector.

#### Instructional Symbols / Definitions



Denotes warnings that may lead to serious physical injury or vehicle damage



Denotes quality processes to be checked prior to moving to the next step

Denotes specific tools that are necessary to complete a step













Hearing Protection

damage



Denotes cautions to be taken to avoid physical injury or electronic component

Denotes cautions to be taken to avoid

vehicle and component damage



Denotes important information to be reviewed during the step

#### **Basic Required Hand Tools**



M10 10mm Deepwell Socket











#### Part Weight (Gross)

1.32	lbs
0.60	kg

## FMVSS 110 Compliance Information


All dealers must determine if the Net weight they have added in the form of all options or accessories, when added to the weight of all Port/Dealer Installed options or accessories, exceeds the lesser of 1.5% of GVWR or 100lbs. If the additional weight does exceed the lesser of the indicated thresholds, a "Load Carrying Capacity Reduced" label must be installed. A black, fine-point, indelible marker must be used to write by hand onto the label, the reduced carrying capacity in kilograms or pounds, which is the total weight of all added options and accessories. Load Label Part Number: NP070 - 09003

# Part Weight (Net) 0.27

## lbs 0.12 kg

# Notes to the installer:

- 1) Read the entire Installation Instructions prior to beginning the installation of the part.
- 2) Make sure the vehicle is completely clean and dry in the area(s) the part is to be installed.
- Ensure the vehicle is properly protected in the area(s) that the accessory is to be installed.
- 4) NEVER place tools on painted surfaces, seating surfaces, dash pad, console or floor carpet/mats.
- Always wear appropriate personal protective equipment, including gloves, safety glasses, etc., when required.
- Record radio presets prior to disconnecting battery power, if needed.
- 7) Roll down the driver's window prior to disconnecting battery power, if needed.




No.	Qty	Description
1	1	Mirror, Auto-dimming w/ HL4, BL & Compass
2	1	Hardware Kit

## Hardware Kit Contents








Follow instructions for proper placement of each component.


Hardware Total	
Haldwale Hotal	
3	


## Radio Presets - record customer preset frequencies if disconnecting battery power


FM1	FM2	FM3	FM4	FM5
FM6	FM7	FM8	FM9	FM10
AM1	AM2	AM3	AM4	AM5
SAT1	SAT2	SAT3	SAT4	SAT5


#### **Electrical Connection Procedure**
























































# Visual Check

Item to be Checked		Result	
	Negative battery terminal re-tightened (Refer to step 10 on page 6).	Battery cable is correctly fastened to the negative terminal.  Nut is properly torqued to 5.0 ~ 6.0 N.m (0.50 ~ 0.60 kgf.m, 45 ~ 52 lb-in).	
	Mirror Torx screw reinstalled and re-tightened	Screw is tightened and properly torqued to: 1.76 N-m (0.18 Kgf-m, <b>15.6 lb-in</b> ).	
	Mirror Jumper Harness 10-Pin connectors	Mirror Jumper Harness 10-Pin connectors are properly connected and locked into accessory mirror and factory harness.	
	Plastic Shroud and Center Cover	Plastic Shroud is fully engaged with windshield anchor clips and Center Cover is engaged with Plastic Shroud.	
	Auto-Dimming	Mirror dims with ignition in the "ON" position when the forward looking photocell is covered. Mirror is clear and does NOT dim with ignition in the "OFF" position.	
	Compass Display	Compass display reads either "C" or a directional heading with ignition in the "ON" position only and NOT in the "OFF" position.	
	HomeLink	HomeLink indicator LED illuminates when each button is pushed with ignition in the "OFF" position.	

## Troubleshooting

Item to be Checked

Mirror does not power up.	Confirm constant power circuit is properly connected. Circuit should have 12V power with ignition in "OFF".
	-Check that factory harness is properly connected to jumper harnessCheck that jumper harness is properly connected to the mirrorCheck that wires are not damaged.
Ť	Confirm ignition-switched power circuit is properly connected.  Circuit should NOT have power with ignition in "OFF", but should have 12V power when ignition is switched to "ON".
	-Check that factory harness is properly connected to jumper harnessCheck that jumper harness is properly connected to the mirrorCheck that wire is not damaged.
Homelink does not work (LED does not illuminate).	-Check vehicle interior lamp fuse.
Homelink does not work (LED does not illuminate when all HL buttons pressed).	-Replace the mirror.
Compass does not illuminate.	-Check that the Compass feature is "ON" with the power buttonCheck vehicle interior lamp fuse.
Auto-dimming function does not work properly (LED does not illuminate).	-Check that the mirror power is "ON" with the main power buttonCheck vehicle interior lamp fuse.
Auto-dimming function does not work properly (LED illuminates, but mirror does not darken).	-Replace the mirror.
Blue Link buttons do not trigger audio or visual message from radio/navigation unit.	-Check that the mirror power is "ON" with the main power buttonCheck harness to ensure connection is made between factory harness and auto-dimming mirrorReinstall factory mirror and ensure Blue Link functions correctly.

# **Jumper Harness Wiring Diagram**

